

# Oil Field Environmental Incident Summary

**Incident:** 20141221163136      **Date/Time of Notice:** 12/21/2014 16:31

**Responsible Party:** CONTINENTAL RESOURCES, INC.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** BARNEY 6-29H1

**Field Name:** BROOKLYN

**Well File #:** 29480

**Date Incident:** 12/21/2014      **Time Incident:** 08:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 155

**Rng:** 98

**Sec:** 29

**Qtr:**

**Location Description:**

**Submitted By:** Patrick Skillestad

**Received By:**

**Contact Person:** Patrick Skillestad  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	20	Barrels	20	Barrels	20	barrels

**Description of Other Released Contaminant:**

Invert

**Inspected:**

**Written Report Received:** 9/23/2016

**Clean Up Concluded:** 12/21/2014

**Risk Evaluation:**

None

**Areal Extent:**

10 ft x 25 ft

**Potential Environmental Impacts:**

Location soil

**Action Taken or Planned:**

Invert was sucked up and contaminated soil was removed. Invert and soil were mixed with fly ash and put into cuttings pit.

**Wastes Disposal Location:** Cuttings pit on site.

**Agencies Involved:**

**Updates**

---

**Date:** 12/22/2014 **Status:** Reviewed - Assigned to Other Agency

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to tank leak, remained on location within the diking according to the report. NDIC retains oversight.